

✓

**TO BE FILLED BY THE INSPECTING OFFICER**  
(Assistant Engineer/Assistant Executive Engineer)

Name of School Vadi Husna Public School(Senior Secondary) Elettil

1. Name of the officer Asst.Engineer Kizhakkoth Panchayath

2. Location Elettil

3. Period for which the certificate is issued 2019-2020

4. Types of building R C C

GF 42m x 6m x 3.7m + 12m x 9m x 3.7m +  
6 m x 8 m x 3.7 m + 12m x6m x 3.7m

FF 42 m x 6m x 3.7m + 12 m x 9m x 3.7m +  
6 m x 8 m x 3.7 m + 12m x6m x 3.7m

SF 42m x 6m x 3.7m + 12 m x 9m x 3.7m +  
6 m x 8 m x 3.7 m + 12m x 6m x 3.7m

5. Nature of defect if any Nil

a) Foundation and basement

b) Superstructure

c) Doors and windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks if any)

6. Any major defects noticed which will render the building unsafe in any manner Nil

7. Whether maintenance work have been done properly Yes

8. Whether the structure is sound or not for conducting classes. Sound enough under normal wind and weather condition.

- Note: 1. The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
2. Any additional observation deemed necessary for the certificate, may be furnished separate with the Certificate.

Certified that the School was inspected by me on 18/01/20 and found to be, fit/~~unfit~~ to conduct classes for the period for the reasons stated above.

Place: Kizhakkoth

Signature

Date: 18/01/20

Designation



[Signature]  
Assistant Engineer  
LSGD Section  
Kizhakkoth Grama Panchayath